

Huntington Trail HOA (Storm) 6.4.25

-----

ST-2 up to ST-1 (216ft. run) 15in RCP

18.4ft. Mild Erosion at joint  
61.4ft. Hairline fracture  
110.4ft. Chip in pipe, no soil infiltration  
111.7ft. Heavy joint erosion with large deposit  
121.8ft. Chipped pipe, no soil infiltration  
123.9ft. Pipe has been bored through with another pipe  
128ft. Medium joint erosion  
144.6ft. Heavy joint erosion  
184.9ft. Building plaster layer through to the end of pipe

-----

ST-2 down to ST-3 (193ft. run) 15in RCP

16.3ft Hairline fracture

-----

ST-3 down to ST-4 (52 ft. run) 24in RCP

Line is ok

-----

ST-4 down to Outfall 1(Plug) (69ft. run) 30in RCP

line is ok